







Návod k montáži
Sprchová zástěna Walk-in HYD-WIF














H=200cm

WIN-519	L=48-50cm	WIN-1019	L=98-100cm
WIN-619	L=58-60cm	WIN-1119	L=108-110cm
WIN-719	L=68-70cm	WIN-1219	L=118-120cm
WIN-819	L=78-80cm	WIN-1319	L=128-130cm
WIN-919	L=88-90cm	WIN-1419	L=138-140cm







1

02



X1

05








X5

06






ST4X30








X5





2




3









4





6



7

