








INSTALLATION MANUAL




Accessory list

X1	X1	X1	X2	X1
X1	X1	X2	X1	X1
X1	X1	X2	X1	X1
X1	X1	X1	X8	X1
4x16 X2	X11	X1	X1	X4





Tool picture




Pencil	Cross screw driver	Drill machine	Tape measure	Silicon gel
Inner hexagon spanner (In the package)	Scissors	Level ruler	Rubber hammer	









SIZE	A(mm)	C(mm)
800	790-805	797-812
900	890-905	897-912
1000	990-1005	997-1012

SIZE	B(mm)	D(mm)
900	890-905	896-911
1000	990-1005	996-1011
1100	1090-1105	1096-1111
1200	1190-1205	1196-1211





9 10
11 12



13 14
15 16

